

	WOOD ITEM	WRA GUIDANCE	EXCLUDE FROM TESTING IF
1	Railway sleepers, Telegraph poles	Always Hazardous	No exclusion all hazardous
2	Timber tiling battens	Potentially Hazardous if - Softwood timber components produced between 1950 and 2007	Pre 1950 or post 2007
3	Roof timbers, pitched roof rafters, flat roof joists	Potentially Hazardous if - Softwood timber components produced between 1950 and 2007	Pre 1950 or post 2007
4	Timber floor joist	Potentially Hazardous if - Softwood timber components produced between 1950 and 2007	Pre 1950 or post 2007
5	External timber doors (2 x GG & 2 X G doors minimal) & frames	Potentially Hazardous if - Softwood timber components produced between 1950 and 1995	Hardwood Painted Pre 1950 or post 1995
6	Timber Window (minimal)	Potentially Hazardous if - Softwood timber components produced between 1950 and 1995	Hardwood Painted Pre 1950 or post 1995
7	External Timber Cladding	Potentially Hazardous if - Softwood timber components produced between 1950 and 1995	Hardwood Painted Pre 1950 or post 1995
8	Fascia and Soffits barge boards or box ends(minimal works)	Potentially Hazardous if - Softwood timber components produced between 1950 and 1995	Hardwood Painted Pre 1950 or post 1995
1	Fence post, rails and pales	Non hazardous unless Creosoted	Non hazardous unless Creosoted
2	Decking	Non hazardous	All excluded
3	Fence Panels	Non hazardous	All excluded
4	Garden Products (Furniture, Tables, Pergolas, Sheds)	Non hazardous	All excluded
5	Plywood sheeting	Non hazardous	All excluded
6	Internal Doors and frames	Non hazardous	All excluded